




Hale School

- ▶ Replace hot water heater – high efficiency system
 - ▶ Second phase of automation system
 - ▶ Auditorium compressor unit
 - ▶ Gym/Auditorium Floors – scuffed and polyurethaned
 - ▶ Domestic drinking water storage tank – cleaned and inspected
 - ▶ New classroom configurations
- 

Center School

- ▶ Door control system – (Card reader system) – now compatible with district and operating well/new software and hardware
 - ▶ Revamped book room
 - ▶ Gym/Auditorium Floor – scuffed and polyurethaned
- 

Florence Sawyer/Emerson

- ▶ Installed/Built reading nook
 - ▶ Domestic water storage tank cleaned and inspected
 - ▶ Some painting
 - ▶ Gym/Auditorium Floors – scuffed and polyurethaned
 - ▶ Fire Control Panel replaced and upgraded for Emerson and Central Office
- 

High School

- ▶ Replaced domestic hot water system – high efficiency system
- ▶ Access hatch created on domestic storage tank – cleaned and inspected
- ▶ Gym/Auditorium floors – scuffed and polyurethaned
- ▶ Locker Repairs/Installation of 500 built-In locks
- ▶ Irrigation system installed on baseball field
- ▶ Added additional parking
- ▶ Leach Field – Engineering process has begun
 - Initial tests completed with DEP witnessed
 - Monitoring wells installed
 - Property surveys completed

Luther Burbank/MRE

- ▶ Gym/Auditorium Floors – scuffed and polyurethaned
- ▶ Smoke detector inspection cleaning and replacement project – 2/3 completed
- ▶ PA System repaired
- ▶ Hot Water replacement (Unanticipated) – Converted to High Efficiency

Summer Maintenance

- ▶ Filters Changed
- ▶ Cleaning of room univents
- ▶ General deep cleaning (ceiling to floor)
- ▶ Drywall/general repairs
- ▶ Cleaning of furniture
- ▶ Cleaning/waxing of floors
- ▶ Hallways
- ▶ Fixture cleaning

