

Facilities Update



Leach Field



- Hydrogeologic Evaluation Report
 - Has been approved by DEP, for the future application for the ground water discharge permit.
- Onsite Engineering
 - Will be designing and sizing the forced main pump system, field pumps and layout of the leaching field.
 - Tennessee Gas for gas line crossing, permitting and putting bid specs together in preparation to go out to bid in the Spring and applying for the ground water discharge permit for Mass DEP



High School Oil Tank

Concrete vault

- Taken on surface/ground water
- Tie down straps snapped resulting in the tank floating and cutting off the oil supply to the school.
- 5000 gallon temporary tank installed.
- Water removed from vault.
- Working with multiple vendors for the best options for the site.

Center School Automatic Float Valve for Fire Suppression System

- Mechanical float valve – Failed.
 - Well running constantly from the domestic water supply.
 - Isolated well until repairs made.
 - Scuba diver brought in.
 - New valve installed.
-
- NFPA 25 inspection and cleaning completed while valve was being replaced.



Center School Boiler Plant

- Increased number of service calls
- Working with manufacture reps for solutions and warranties

